

CÓDIGO	MODELO
--------	--------

## AIWA

<b>KFT 3AA</b> 294X	AR 205 (Vide Equivalente CCE-49)	AW - 01 CCE - 49
<b>KFT 4AA</b>	AR 295RH	AW - 02
<b>KFT 2AA</b>	AR-145 (Vide Equivalente CCE-53)	AW - 03 / CCE- 53

## BAYSONIC

<b>FCK 14A028</b>	CB -14 A ( Vide Equivalente Semivox - SS-04 )	BY - 01 SS - 04
<b>154 - 165D</b>	CB - 20	BY - 02
<b>FCM 20A016</b> TLF 70162	CB 20 A / SINGER TV 3920	BY - 03

## BROKSONIC

<b>FCC 1415AL</b>	GTV 4545 LSTC / Foco Baixo (duplicidade) CTVG 4545LSTC	BK - 01
<b>FCC 2015AL</b>	GTV 5454	BK - 02
<b>FCC 2015FL</b> ( Foco ALTO )	CTVG-5454-LST GTV 4545 LSTC / Foco Alto (duplicidade)	BK - 03
<b>3.219.004</b>	GT 5454 LST	BK - 04
<b>3213002</b> 3213003	4545LST 14"VT-1421	BK - 05
<b>KFS60282</b>	CTVL4545 14"	BK - 06
<b>DCF 2077</b>	4545 LSB	BK - 07
<b>BSC 23-1108</b>	BROKSONIC CTVC - 4545	BK - 08

## CCE , BLUE SKY, DAEWOO, PROVIEW

<b>TAT 1401 A</b>	HPS 1415 B, 1415 C HPS 1425 A, 1425 B HPS 1450 B, 1465, 1465 A, 1465 B	CCE - 01
<b>TAT 1402 A</b> TAT 1402 B TAT 1402 C	HPS 1465 Z, 1470 B, 1470 K, 1470 Z, 1470 ZJ, 1490 C HPS 1485, 1485 B, 1485 G, 1485 ZG	CCE - 02
<b>TAT 1403 A</b> TAT 1403 B	HPS 1465 C, 1465 ZC, 1465 ZD, 1465 ZG, 1465 ZH HPS 1470 ZC, 1470 ZD, 1470 ZG, 1470 ZH HPS 1485 D, 1485 ZC, 1485 ZD HPS 1490 D, 1490 ZC, 1490 ZD HPS 90A/90C	CCE - 03
<b>TAT 1404 A</b>	HPS 1465 ZE, 1465 ZF, 1465 ZI HPS 1470 ZI, 1470 ZE / ZF HPS 1485 E, 1485 I, 1485 F, 1485 ZE, 1485 ZF, 1485 ZI HPS 1490 CD, 1490 E, 1490 F, 1490 I, 1490 ZE, 1490 ZF, 1490 ZI	CCE - 04
<b>TAT 1405 A</b> TAT 1405 B TAT 1405 D	HPS 14B, 14E, 14R, 14RB, 14RC, 14RD HPS 1470 AA, 1470AP, 1470 BB, 1470 CC, 1470 DD, 1470 EE, HPS 1470FF, 1470P, 1470Q, 1470R, 1470S, 1470T, 1470U HPS 1480, 1480 B, 1480 C, 1480 D HPS 1481, 1481 B, 1481 C HPS 1492 C	CCE - 05
<b>TAT 1406 A</b>	HPS 1401, 1470 V, 1481 E, 1481 Y	CCE - 06
<b>TAT 1407 A</b> TAT 1407 B	HPS 1401 D, 1401 HPS 1492	CCE - 07
<b>IAT 1409 D</b>		
<b>TAT 1412A</b>	HPS 141B, 141C, 141D, 141G, 142B, 1405, 1407F, 1407G, 1407E HPS 1407S, 1423 , MT14NEW, 1407B, 1405B	CCE - 09
<b>TAT 1414 A</b>	HPS 14BPS	CCE - 10
<b>TAT 1420 A</b>	CCE 1405 H	CCE - 11

FBT/FBT200290AA (TRFLUODACE)/TRFLUODACE	( Vide Equivalente Goldstar - GD-03 / LG - 03 )	GD - 03 LG - 03
<b>DCF 1577</b> DCF 1577 A1	HPS 1491, 1495, GTV 4545 LSTC ( Vide Equivalente Precision - PX-02) - NISATO 1445 NCT	CCE - 13 PX - 02
<b>TAT 2001 A</b>	HPS 2010 B, 2025 A, 2025 B, 2050 B, 2065, 2070	CCE - 14
<b>TAT 2002 A</b> TAT 2002 B	HPS 2065, 2065 Z, 2065 ZB, 2065 ZC, 2065 ZD HPS 2070, 2070 B, 2070 Z, 2070 ZB, 2070 ZC HPS 2085, 2085 B, 2085 C, 2085 ZB, 2085 ZC HPS 2090, 2090 B, 2090 C, 2090 ZB, 2090 ZC	CCE - 15
<b>TAT 2003 A</b>	HPS 2065 ZD, 2065 ZE, 2070 ZD, 2070 ZE, 2070 ZF D/E/F, 2090FD	CCE - 16

	HPS 2085 D, 2085 E, 2085 F, 2090 B, 2090D, 2090 E, 2090 F, 2090AP	
<b>TAT 2004 A</b> TAT 2004	HPS 2070P, 2070Q, 2070R, 2080F, 2080R, 2081B, 2080H, 2081D HPS 2070X, 2070 ZD, 2070 ZE, 2070 ZF HPS 2085 D, 2085 E, 2085 F, 2090 B, 2090 D HPS 2090 E	CCE - 17
<b>TAT 2005 A</b>	HPS 2080 C, 2080 E	CCE - 18
<b>TAT 2006 A</b> TAT 2006 B TAT 2006 C TAT 2006 D	HPS 2070 S, 2070 V, 2080 B, 2081, 2081 C, 2080	CCE - 19
<b>TAT 2007 A</b>	HPS 2080 D	CCE - 20
<b>TAT 2008 A</b>	HPS 2092, 2092 B, 2092 C, 2092 D	CCE - 21
<b>TAT 2009 A</b> TAT 2009 B TAT 2009 C TAT 2009 D TAT 2009 E	HPS 1402 C, 2001,2001 B,2001 C,2001 D,2002,2002 D,2003, HPS 2004 A/B,2006, 2003 B/C, 2009 D, 2001 I, 2001 G MATSUI / MT-20 BLUE SKY - TV 20 BLK	CCE - 22
<b>TAT 2011</b>	HPS 2007C, 2023, MT20NEW	CCE - 23
<b>TAT 2012</b>	HPS 2005, 2005G , 2007, 2007F , 2007H , 2007S , 2008, JC20, HPS 2071, HPS 2044.	CCE - 24
<b>TAT 2020</b>	HPS 2005 H	CCE - 25
<b>FSV 20 B 013</b>	BLUE SKY - TC-2033V (Vide Equivalente Cinerall - CN-04)	CCE - 26 CN - 04
<b>FCM 2015 CL</b> TLF 70018A	HPS 2010, 2010A, 14 ( 10 Pinos ) ( Vide Equivalente Samsung - SS-17 )	CCE - 27 SS - 17
<b>DCF 2077</b> DDF 9802A	HPS 20 VR, 2091, 2095 ( Vide Eq.Paxan e Precision - PX-03/ Philco - PC-07/ Telefunken - TF-03)NISATO 2045 NCT - BROOKSONIC - 4545 LSB.	CCE - 28 PX-03/PC-07 TF - 03
<b>TAT 2101 A</b>	HPS 2181 A, 2181 B, 21 E	CCE - 29
<b>TAT 2102 A</b>	HPS 20 EP, 21 EB	CCE - 30
<b>BSC 23-6910</b> FO 1415 (DNF)	BLUE SKY - 1433 (Vide Equivalente Cinerall - CN - 01)	CCE - 31 CN - 01
<b>TAT 2701 A</b>	HPS 2780, 2781 B, 2980 (IMPORT.)	CCE - 32
<b>TAT 2702 A</b>	HPS 2706, 2706 B	CCE - 33
<b>TAT 2704 A</b>	HPS 2706C, 27BLK	CCE - 34
<b>TAT 2901 A</b> MSU1 FHC506 MSU1FHG50 6	HPS 2980, 2981, 2981 B, 2981 C, 2981 D HPS 2980 (IMPORT.)	CCE - 35

### CCE , BLUE SKY, DAEWOO, PROVIEW

<b>TAT 2902 A</b>	HPS 29E "B"	CCE - 36
<b>TAT 2903 A/B</b>	HPS 2902, HPS 2901 B, HPS 2901	CCE - 37
<b>TAT 2904 A</b> TAT 2904B	HPS 2904E, 2906 B, 2906C, 2906D , 29BLK , 29BLKB,29BLKC, 29BLKD, 2904A, 2904B	CCE - 38
<b>TAT 2907 A/B</b>	HPS 2906E, 2906F, 2910 , 2910B, 2910C, 2910E	CCE - 39
<b>TAT 2908 A</b>	HPS 2908 C	CCE - 40
<b>TAT 2908 B</b> TAT 2908C	HPS 2908	CCE - 41
<b>FBT 3380</b> TAT 3380	HPS 3380	CCE - 42
<b>TAT 3401 A</b>	HPS 33 R / 33 RB	CCE - 43
<b>KFS 60226 / B</b>	HPS 1425, 1450 A, 1450 R, 1450 C, 1495, 1495 B, 1450 AB, 1495 BR, 1491 20AV49 (PHILCO USHUAIA - ARGENTINA)	CCE - 44
<b>KFS 60266</b>	HPS 2025, 2050 A, 2050 C, 2050 R, 2095, HPS 20 DAYTON DTH 1427 FS	CCE - 45

(Foco) <b>NF 7401</b> FTB 7401C	HPS 1430 R HPS 20, 2015, 2030 R	CCE - 47
<b>TAT 2906B</b>	HPS 2901	CCE - 48
<b>KFT 3AA 294X</b>	HPS 2003F, TVAR205 (Vide Equivalente Aiwa - AW-01)	CCE - 49 AW - 01
<b>KFT 4AW 332Y</b> KFT 4AA 332X	HPS 2912	CCE - 50
<b>BSC 28-2101</b> C 1226216C	BLUE SKY - TC-2932 / 2933 (Vide Equivalente Cinerall CN-08)	CCE - 51 CN-08
<b>FSA 25023 S</b>	DAEWOO - DTH 14Q2FS / DVX 14F6N	CCE - 52

**3/22**

<b>KFT 2AA 293X</b>	HPS 1403G / 2003G - (Vide Equivalente Aiwa - AW-03)	CCE-53/ AW-03
<b>FSA 28014M</b>	DAEWOO - DTH 20QTFS / <b>DTH20J1 FS</b>	CCE - 54
<b>MC-FBM-001</b>	TVP5C, TVP6/B/C, TV65/AUDAX	CCE - 55
<b>MC-FBC-002 MF-</b>	TVP7, TVP7 B	CCE - 56
<b>MC-FBM-003 BSH</b>	TVP8, TVP12, TVP12B/VS	CCE - 57
<b>TAT 2104</b>	HPS 2118, HPS 2185 FS / BLK 2105, HPS 2171 (DUPLICIDADE)	CCE - 58
<b>KFT 4AW 371Y</b>	HPS 2912B	CCE - 59
<b>TAT 14101A</b>	(Vide Equivalente SH-21)	CCE - 60 / SH-21
<b>TAT 2982A</b>	HPS 2982 , 2991, TVD 2911 VS , TP 2958	CCE - 61
<b>TAT 2909 A</b> TAT 2971A/B	HPS 2909 / 2971 (DUPLICIDADE) TVD 2901 (DUPLICIDADE)	CCE - 62
<b>BSC 27-G0101 F</b>	BLUE SKY - TC PL 2919 P (Vide Equivalente Cinerall CN-12)	CCE - 63 / CN-12
<b>FUH 30A005</b>		CCE - 64 / GT-25
<b>MC-FBM-004</b>		CCE - 65
<b>MC-FBM-018</b> (VM-14AF)		CCE - 66
<b>BSC 29-0192F</b>	CCE - HPS 2991 FSC, HPS 2997FS , <b>HPS2971C</b>	CCE - 67
<b>TAT 3301A</b>	HPS - 3301	CCE - 68
<b>BSC 29-0157E</b>	HPS 2985/B/C/D ; TVD2901 F ; HPS 2988 (DUPLICIDADE)	CCE-69 / CN-21

**CCE , BLUE SKY, DAEWOO, PROVIEW**

<b>CFB2-005 / 43-74-</b>	TVP 105	CCE - 70
<b>MTI LTC-042</b> MF-6950B	HPS 2971 <b>FSG "CUIDADO" DUPLICIDADE LER MANUAL</b> <b>HPS 2983</b>	CCE - 71
<b>BSC29-0178V</b>	PROVIEW TL29N6T / TL 29NSP / <b>TL - 29N6P</b>	CCE - 72
<b>BSC25-0274D</b>	BLUE SKY/ CCE HPS1471 E/F/G HPS1473D	CCE - 73
<b>BSC25-0206H</b>	OCE TP 2148 HPS2185FSB / HPS2157FS / HPS2171 FS / HPS2177H , <b>HPS2199, HPS2197 (DUPLICIDADE) HPS 2185FS</b>	CCE-74 / CN-24
<b>BSC25-021 0F</b>	CCE HPS2171 FSG / 2185 FSE	CCE - 75
<b>BSC25-0274E</b>	BLUE SKY/ <b>2044 / CCE HPS 1470 / HPS2073</b>	CCE - 76
<b>BSC31-0104K</b>	CCE HPS 3406 HPS 3407	CCE-77 / CN-25
<b>TAT 2105</b>	<b>HPS 2171 FS HPS 2185 FSD</b>	<b>CCE-78</b>
<b>BSC 29-0193K</b>	<b>TVS 2910FS/FS</b>	<b>CCE-80</b>
<b>TAT 2703A</b>		<b>CCE-81</b>

**CINERALL, BAKOSONIK, CYBER VISION**

<b>FO 1415 (DNF)</b> BSC 23-6910 BSC 25-2701	CINERALL - TC-1432 / 1433 (Vide Equivalente Blue Sky - CCE-31) 14TF	CN - 01 CCE - 31
<b>154-164 F</b>	CTVG 5050 ( Vide Equivalente Panasonic - P S-11 )	CN - 02 / PS -
<b>FSV 20 B 012</b>	( Vide Equivalente Samsung - SS-14 )	CN - 03 / SS -
<b>FSV 20 B 013</b> C1226214 A C1226215 A SN:	CINERALL - TC-2032 / 2033V (Vide Equivalente Blue Sky - CCE-26)	CN - 04 CCE - 26
<b>FSA 27018 M</b> DCF 2077Z	1411 / 1422 / 2011 / 2022 CVT 1485 / <b>CCE HPS2091</b>	CN - 05

<b>BSC 28-2101</b> C1226216C	CINERAL - TC-2932 / 2933 (DUPLICIDADE) / 29BD (Vide Equivalente)	CN - 08 CCE-51
<b>FFA 94024L</b>	TS 2975	CN - 09
<b>DFE 98014</b>	14" E 20" CINERAL TC 2933 (DUPLICIDADE)	CN - 10
<b>BSC 27-G0101F</b>		CN-12/CCE-63
<b>MCG-21A26</b> SN: 11226230		CN - 13
<b>PWL - 15</b> BSC 25-N0522	CINERAL - TS 2977 CYBER - VISION MDTF 2948 / <b>TC PL2932(DUPLICIDADE)</b>	CN - 14 PH-226
<b>BSC 28-N2328</b>	BLK 2932 / <b>TC PL2932(DUPLICIDADE)</b>	CN - 15
<b>OV2094 - A - H - I</b> (08301 FT---)	CINERAL - 2070 / MDTF 2948 / TC 2034 / TC 2048 CYBER TCPL 2110 / TC 1470 M / TC 1433 N / TC 2023 / TV -1444	CN - 16 PH-147
<b>MCJ-29A005</b>	TS 2932 / TS 2933	CN - 17
<b>BSC 24-N0102C</b>	CINERAL	CN - 18

4/22

( OV 2094 )		
<b>BSC 25-N0302</b> ( OV 2094 )	CINERAL TC-2032 TC PL-2110	CN - 19
<b>BSC 30-N2570</b> 6174917003A	CINERAL	CN - 20
<b>BSC 29-0157E</b>	CINERAL / CYBER CB 2905	CN-21/ CCE-
<b>3220004</b>	CINERAL VT 0950 M	CN - 22
<b>BSC28-N2313A</b>	TC PL-2901	CN - 23
<b>BSC25-0206H</b>	CINERAL / CYBER VISION TP 2148 HPS2185FSB / HPS2157FS / HPS2171 FS HPS2177H	CN-24/ CCE- 74
<b>BSC31-0104K</b>	CIBER VISION / CCE HPS 3406 HPS 3407	CN-25/ CCE- 77
<b>BSC 26-01 N4004K</b>	<b>PL-2910 (CINERAL)</b>	<b>CN - 26</b>
<b>BSC 25-0272Q</b>	<b>21 PCIN 0305</b>	<b>CN - 27</b>
<b>JF0501-21130</b>	<b>29 PCIN 0507</b>	<b>CN - 28</b>
<b>BSC 25-0252T</b>	<b>21 PCIN 0405 / 14 PCIN 0401</b>	<b>CN - 29</b>

### CONTINENTAL, COUGAR, EMERSON

<b>101-21002-03 A</b> LCE CF-0359	EMERSON	CT - 01
<b>FCK 1415 JL</b>	EMERSON - 2122 C, TECSONIC T14RWC, SEMIVOX TS 14C1R	CT - 02
<b>154 - 189 H</b>	3352 Z GT - 9313 ( CONTINENTAL )	CT - 03

### CONTINENTAL, COUGAR, EMERSON

<b>3214014</b>	EMERSON - 1465B	CT - 04
<b>3214015</b>	EMERSON - TC-1465	CT - 05
<b>154 - 138B</b> 11226086	EMERSON - TC-1405A	CT - 06
<b>3.220.030</b>	EMERSON - TC-2066	CT - 07
<b>F 2005 CE (H)</b>	COUGAR - CTV 1413 / 2013	CT - 08 SH - 18
<b>3.220.023</b>	VT 2020	CT - 09

### GOLDSTAR

<b>154 - 164 E</b>	GTV 5050, CB 14	GD - 01
<b>154 - 177 J</b>	CP1413, CP14 A 13, 14 A 40, 14 A 80, 14 CB 80, 14 A 82, 20 B 70, 20 CB 80, 20 A 82 (Vide Eq. Gradiente - GT-02/ LG-02/ Philco - PC-04/ Samsung - SS-06 )	GD - 02 GT 02 LG -
<b>154 - 179 M</b>	CP 29 C 10 ( Vide Equivalente LG-03 e CCE-12 )	GD - 03 LG - 03 CCE
<b>154 - 207 A 154 -</b>	CANGURU KP 14V30 , 20A80 (Vide equivalente Gradiente - GT-03)	GD - 04 GT - 03

		04 LG - 04
<b>154 - 375 C</b>	( Vide Equivalente LG-05/ Samsung - SS-08 )	GD - 06 LG-05 SS
<b>154 -</b>	GOLDSTAR - CNT 9175	GD - 07
<b>154 - 103C</b>	GOLDSTAR - CP-33C60 / LG CP-34C62P	GD - 08 LG-72

### GRADIENTE, JVC, MONITOR DE SEGURANÇA

<b>FCV 1410 E 06</b> ( 571 395 001 902 )	GT 1410, GT 1411, 14 C 5170 ( Vide Equivalente Telefunken - TF-01 )	GT - 01 TF - 01
<b>154 - 177 J</b> ( 571 476 001 902 )	GT 1420, 1422, 2020, 2022, 2025 (Vide equivalente Goldstar - GD-02 / LG-02 / Philco-PC-04 / Samsung - SS-06)	GT - 02 GD - 02 LG - 02 PC - 04 SS - 06
<b>154 - 207 A</b> ( 951 167 001 901 )	GTV142 (TV E VIDEO) ( Vide Equivalente Goldstar - GD-04 )	GT - 03 GD - 04
<b>154 - 375 A</b>	( Vide Equivalente Goldstar - GD-05/ LG-04/ Samsung - SS-07 )	GT - 04 GD - 05 LG - 04 SS - 07
<b>FCV 2010 E 02</b> FCV 2011	GT 1410, GT 1411, GT 2010, GT 2011, GT 2015 20 C 5170	GT - 05 TF - 02 <b>5/22</b>

( 571 391 001 902 )	( Vide Equivalente Telefunken - TF-02 )	
<b>FCV 2010 E 09A</b> 230934	( Vide Equivalente RCA-08 / Zenith -ZT-01 )	GT - 06 RCA-08 / ZT-01
<b>CJ 27773 / 00AJ1</b> CE 42205-002 G 27327-063F	JVC - C 1485BR / C 1484	GT - 07
<b>CJ 27898</b> ( 571 418 001 902 )	HRM 29 PS / HRM 33PS / HRM 37PS JVC - 31 BX4	GT - 08
<b>CJ 28069</b>	AV 2196 SAH, AV-T-2172	GT - 09
<b>CJ 28111</b>	JVC C 1486, CT 1471	GT - 10
<b>CJ 28212</b> ( 571 448 001 902 )	HRM 290 PS / HRM 330 S / HRM 370 PS JVC - AVB 2973 - AVB 3373	GT - 11

### GRADIENTE, JVC, MONITOR DE SEGURANÇA

<b>CE 41899-00A</b>	GRADIENTE - 335 COM PIP / JVC - AV 31 BP4 / AV-3150	GT - 12
<b>CE 42211-00B</b> CE 42031-00C 571 414 001902	GT - 2825 / 2925	GT - 13
<b>CE 42674-001J1</b> ( 571489001902 D )	HT - M 277S / 299S / 29 Mi / 29i JVC- AV-T2977	GT - 14
<b>47105380</b> BSC 26-5620 ( 571 439 001 902 )	HRM 290 S	GT - 15
<b>TCV 50 B 01</b> FCV 1422L01	JVC - 2120 (Vide Equivalente Pekonic - PX-05)	GT - 16 PX - 05
<b>6174V - 8004 A</b> 6174V - 8004 D 6174V - 8005 C ( 5700070019	2030 / 2033 / M - 20i / 1430 / 1433 / 14 Mi Monitor de Segurança - SM-14 / CFTVSM-20 ( Vide equivalente LG-18 )	GT - 17 LG - 18
<b>QQH 0025-001</b>	HT-M 344S	GT - 18
<b>CE 42374-00-CKJ1</b>	JVC - AV 35BP4U / GRADIENTE - HRM - 37PS	GT - 19
<b>6174Z - 6012 Q</b>	Monitor de Segurança - 29MI (DUPLICIDADE)	GT - 20
<b>CE 41735-00A</b>	GT 29S / S-28	GT - 21
<b>2436214 (MD14L)</b>	GT 2010	GT - 22
<b>JF 0501-19555</b>	GBT-2011 / TV-2021 / TV-2020 - TV-1421	GT - 23 / PH 400
<b>FUH 30A006</b>	TF-2953	GT - 24
<b>FUH 30A005</b>	TV - 2925	GT - 25 / CCE- 64
<b>6174Z - 6512B</b>	TV - 2924	GT - 26
<b>6174Z - 6012X</b>	NEXT 29L / TV 2920	GT - 27
<b>FFA 97031 L</b>	TV 2922 / GBT 2911 / TV 2920 / GBT2910	GT - 28
<b>FFA 97038L</b>	TVD 2951	GT - 29
<b>6174Z - 6051 B</b>	TF 2952	GT - 30
<b>JF0501-19563</b>	TF 2150	GT - 31

B/C 08292FT...		GT-33/PH-255
JF 0501 -19321	TV 1423	GT -34/PC - 67

## GRUNDING

2436912 NCO 8L	GT 2012 A GT 1412 / 2012 / 2112	GR - 01
1142.5046	( TV + VIDEO ) TVR 3701 SV , TVR 3710	GR - 02

## KIREY, FIRST LINE

FC	FIRST LINE ( Vide Equivalente Semivox - SS-02 )	KY-01 / SS-
FC	KTV 1414 / TS 14 CIR	KY - 02
FA 2017	FIRST LINE - T 20 AW ( Vide Equivalente Semivox - SS-19 )	KY-03 / SS- 10
FA 2019	KTV 2020 / TS 20 CIR	KY - 04

## LG

154 - 103 D	CP 29 C 42 / P	LG - 01
154 - 177 J	CP 14 B 84, CP 20 B 84, CP 20 B 85, CP 20 K 40, CP 14 A 82 (Vide equivalente Gradiente-GT-02/Goldstar-GD-02/Philco-PC-04/Samsung-SS-06)	LG - 02 GT - 02 GD - 02
154 - 179 M	CP 29 C 84 M, CP 29 C 85 M, CP 29 C 85 (Vide equivalente CCE - 12 / Goldstar - GD - 03)	LG - 03 CCE-12 / GD- 03

## LG

**6/22**

154 - 375 A	(Vide equivalente Goldstar - GD-05, Gradiente - GT-04, Samsung - SS-07) CP 20 J 20	LG - 04 GD - 05
154 - 375 C	( Vide equivalente Goldstar - GD-06, Samsung - SS-08 )	LG - 05 GD - 06 / SS -
6174Z - 6002 C	SM - 14	LG - 06
6174V - 6002 G 6174Z-	CP 14 K 40, 14 K 42, RP 20 CB 62 (DUPLICIDADE)	LG - 07
6174V - 6002 J	RP 21 CA 85	LG - 08
6174V - 6002 U BSC26-N2121(N)	RP 20 CC 20 , 20 CB 200	LG - 09
6174V - 6003 J	CP 29 K 30	LG - 10
6174Z - 6005 D	CN-29 Q 1 0P , 29 Q 12P	LG - 11
6174Z - 6012 D	CP 29 C 85	LG - 12
6174Z - 6012 F	( Vide Equivalente Philco - PC-33 )	LG - 13
3210-94714-010 6174Z - 6012 N	CP 25 Q 20	LG - 14
6174Z - 6031 A	CP 29 Q 50 , CP 29 Q 20 (DUPLICIDADE)	LG - 15
6174Z - 6032 A	CP 21 Q 22	LG - 16
6174Z - 6040 B	CP 14 J 52	LG - 17
6174Z / V- 8004 A 6174V - 8004 D 6174V - 8005 C	CP 14 B 85, CP 20 B 15, CP 20 B 85 CP 20 J 52 , 20 K 40 , CP 20 J 50 20 K 70 , 20 B 86 , 24K70 ( Vide equivalente Gradiente - GT-17 )	LG - 18 GT - 17
6174Z - 6040 C		LG - 19
6174V - 6003 M BSC 30-	CP 25Q22	LG - 21
6174Z - 6051 B JW-3	29"	LG - 22
6174V - 7001 A FSA	CP - 20B15 / 20K40 / 20B85	LG - 23
6174Z - 6012 U		LG - 24
4410Z - A001 G	RETRO 42"                    1 ENTRADA / 1 SAÍDA (CAPACITOR)	LG - 25
6174V - 5003 B BSC 28-N2324	29CC25, 29CC26, 29CC90	LG - 28
6174V - 5003 G BSC 28-N2331	29K30A	LG - 29
6174Z - 6035 D	WP 3210 P , WP 32Q10P	LG - 30

<b>6174Z - 6003B</b>	RETROPROJETOR	LG - 32
<b>6174V - 6006C</b> BSC23-N0115	CP 21 Q24A	LG - 33
<b>6174Z - 5004A</b>	29" CP 29Q54 (duplicidade)	LG - 34
<b>6174V - 6003X</b>		LG - 35
<b>6174V - 5003L</b> BSC 28-N2334		LG - 36
<b>6174V - 5003A</b> BSC28- N2325	RP 29FA30A	LG - 37
<b>6174Z - 6004F</b>		LG - 38
<b>6174V - 6006J</b> BSC 26-N2123		LG - 39
<b>6174V - 5003R</b> BSC 25-N1537	RP 29FF80 , RP 29FA35A	LG - 40

## LG

<b>6174V - 6006V</b> BSC 25-N1651	RP 21 FS4R-L6 CP 15Q 90	LG - 41
<b>6174V - 5013A</b> BSC 28-N2355	CP 29K35A	LG - 42
<b>154-238A</b>	CP 29H90P	LG - 43
<b>4410Z - A001 P</b> Divisor 1 entrada e 3		LG - 44
<b>6174V - 6017A</b> JF 0501-19975	RP 14CB25 20CD2R	LG - 45
<b>6174V - 6010C</b> 6174Z - 6035W	RI 34FC32P	LG - 46
<b>6174V - 5007B</b> 6174V - 5007A	RETRO 54NA40PA 44" RP 57NP60P / <b>RP 54NA20TA</b>	LG - 47
<b>6174V - 6010F</b> 6174Z - 6035X	RP 29FC40P RP 20FC40P	LG - 48
<b>6174V - 6010A</b>	RP 32FZI224	LG - 49
<b>6174V - 6010D</b>	<b>ATENÇÃO: LER MANUAL! RP 32FC12P</b>	LG - 50

7/22

BSC29- 5572		
<b>6174V - 6006W</b>	RP 21 FE85G	LG - 51
<b>6174V - 5017A</b> BSC25 - N1545	29 CC 9 LR	LG - 52
<b>6174Z - 6005S</b>	CP 29Q30B	LG - 53
<b>6174V - 5013C</b> BSC30 - N2558	RETRÔ RP 44NA48-P	LG - 54
<b>BSC26 - N2137</b> EBJ 37 038602	CP29FX5CL (DUPLICIDADE)	LG - 55
<b>BSC28-3965N</b>	CP29FX5CL (DUPLICIDADE)	LG - 56
<b>154-207C</b> 154-375A	CP- 20B84	LG - 57
<b>6174V-6003T</b>	CP - 29Q12P	LG - 58
<b>BSC26-N2138</b> EBJ 37 038603	29FS 4RLG / <b>29FU 1 RS</b>	LG - 59
<b>BSC 25-N0363</b> 6174913002 AEBJ 34	21 FU 4RLG - 21 FV 1 R	LG - 60
<b>BSC 24-3368J</b> EBJ 38 957401		LG - 61
<b>4410Z - A001 L</b> Divisor 1 entrada e 3	<b>4410Z-A001 G / 4410Z-A001 P</b>	LG - 62
<b>6174V-5003C</b>		LG - 63
<b>6174V-6003B</b> BSC28-N2314	CP 29C 85	LG - 64
<b>6174Z-5003U</b>		LG - 65
<b>F6174V-5003W</b> BSC 29-N2464	29FS4RLG	LG - 66
<b>6174V-6004E</b>		LG - 67
<b>BSC30-2563</b>		LG - 68
<b>BSC24-3366J</b> 6174913002A	21FS4RLG	LG - 69
<b>BSC28-3965N</b> 6174917004A		LG - 70
<b>6174V-6006M</b>	LG 21 FX5RL	LG - 71
<b>154 - 103C</b>	LG CP-34C62P / GOLDSTAR CP-33C60	LG - 72 / GD

5001A		
154-100D	RP 32A030D	LG-74
6174V-5003Y BSC 29-N2478		LG-75
BSC 24-39202		LG-76

### MITSUBISHI , EVADIN, AIKO

334 B 06209 334 B 06208	TC 2001, 2002, 2003, 2020, 2021 , 2602	MT - 01
334 B 07409		MT - 02
334 B 07601 840.000.141.142	VS 403R (40 Polegadas) / TC-3701	MT - 03
334 B 08201 (Foco ALTO)	TC 1441, 2030, 2031, 2034, 2040, 2041 ( Foco Alto )	MT - 04
334 P 11501	TC 2602	MT - 05
334 P 13001 334 B 08202 334 P 49000	TC 1441, 2030, 2031, 2034, 2040, 2041 ( Foco Baixo )	MT - 06
NF 7404 E	TC 2050, 2051, 2090, 2091, 2094	MT - 07
334 P 18102 ( 2 FOCUS )	29 FS	MT - 08
334 P 18504	TC 21 FC , 2121 FC	MT - 09
334 P 19501	TC 1492 / 2034	MT - 10
334 P 20001	TC 1492, 1498	MT - 11
334 P 20101	TC 2051, 2054, 2060	MT - 12
334 P 21202 334 P 21203	29° TC - 2999 / TC - 2998 / TC-2990	MT - 13
334 P 229B1/C1	TC 1499, 2097, 2098, 2099, 21 S	MT - 14
334 P 22901	TC - 2198	MT - 15
334 P 24801 ( 840-000671-247 )	TC 2909 C	MT - 16

8/22

334 P 25901	TC 1409, 2009	MT - 17
334 P 27201 KFT 3AA 226C	TC 2018, 2018 PS	MT - 18
334 P 27301 CT - 8932	TC 1418 , 2018, 2118	MT - 19
334 P 27401	TC 2918 P S	MT - 20
334 P 23101	33" TC-3398 (DUPLICIDADE), TC-3498 , CS 31303	MT - 21
KF 58383 P	33" 3398 (DUPLICIDADE)	MT - 22 PH -220
334 P 265A10	TC 3309	MT - 23
334 P 272A10 BSC 27-0107A		MT - 24
BSC 27-0104B	TC-2004ST / 2010 / TC - 1410	MT - 25
334 P 23105		MT - 26
BSC 27-0167S 840-00001-247	TC 2910 (DUPLICIDADE)	MT - 27
BSC 27-0177R		MT - 28
BSC 27-0106R	FP 2901 AIKO	MT - 29
6174Z-6007A 334	TC 2018 CS-3520	MT - 30
KFT 3AB-126C		MT - 32
JF0501-3547	AIKO 2910 (DUPLICIDADE)	MT - 33
OLF 04508-F	TC27G31V,33V60, PANA 29V60	P S - 01
TLF 14427 F	PVM 2050 TV + VÍDEO (CANGURU)	P S - 02
TLF 14470 F	29 V 50 , 29 V 60	P S - 03
TLF 14531 FV 9 pinos	TC 209 S, 210 S, 210 US, 215 M, 211 N, 212, TC 212 M, 213, 214 , 215 N	P S - 04
TLF 14532 F	TC 141 N, 142 M, 143 M, 161 M, 162 M	P S - 05

<b>TLF 14534 F 2</b> 9 pinos	TC 144 M, 145 M, 146 M, 163 M, 164 M, 165 M	PS - 07
<b>TLF 14731 F 9</b> pinos TLF 14731 F-1	TC 14R1 M , 144, 145 M, 146 M, 163, 164 M, 165 M	PS - 08
pinos	TC 14 C1, 14C1U, 14 D1, 16 C1, 16D1, 16D1V	PS - 09
<b>TLF 14731 F-</b>	14 C2, 14 D2, 14R1 M, TC-13C1 U, TC-14D1U, TC 20CZ	PS - 10
<b>154 - 164 F</b> KFS 60893	1401MN / 1402 MN , TC 1433 ( Vide Equivalente Bakosonic - CN - 02 )	PS - 11 CN - 02
pinos	TC 20 A2, 20 C2, 20 D2	PS - 12
pinos	TC 29 AS2, TC 29 AV1	PS - 13
<b>TLF 15541 F</b> 10 pinos	TC 20 AS2, 20 AS4	PS - 14
<b>TLF 15564</b> 10 pinos	TC 20 BS 5, TC 20 C 4, TC 20 C 5, 20 D 4, 20 D 5	PS - 15
<b>TLF 15615 F2</b>	PT - 51 G 40 U ; TVC 21 V 50	PS - 16
<b>TLF 15626 F</b> 10 pinos	TC 14 C 4, TC 14 C 5	PS - 17
<b>TLF 15644 F1</b> TLF 15644 F	TC 14 B 7, TC 14 C 20, TC 20 A 7 (duplicidade) , TC 20 B 7, TC 20 C 20, TC 20 C 7, TC 20 C 21 , 20 C 6	PS - 18
pinos	TC 20G7	PS - 19
<b>KFT 2AB 095F</b>	14A8	PS - 20
<b>KFT 2AB 281 F1</b>	14A9 , 14A10, 14A12 (DUPLICIDADE)	PS - 21
<b>KFT 2AB 287F1</b>	14A10	PS - 22
<b>KFT 3AB 096F</b>	TC 20 A 8, 20 A 12 (TRIPLICIDADE) / TC 20A01	PS - 23
<b>KFT 3AB 119F1</b>	TC - 20G9 (DUPLICIDADE) , P S 20G11	PS - 24
<b>KFT 3AB 280F1</b> KFT 3AB 281 F1	TC 20A9 , 20A10P , 20A12 (TRIPLICIDADE)	PS - 25
<b>KFT 4AB 055F</b>	TC 29 A 8 , TC 29A9 (DUPLICIDADE) , 29 A 7	PS - 26
<b>KFT 4AB 143F</b>	TC21G11 (DUPLICIDADE), 27G23W , TC29A9 , 29G9L, 29G11, 29G12, 29A12 29A10 / 29A11/ 29A12	PS - 27
<b>TLF 4 G 503 F</b>	TC 14 C 6, TC 14 C 20, TC 20 C 6, TC 14 C 7, TC 14 A 7 , 14 C 21	PS - 28
<b>TLF 6028 F</b> 9 pinos	TC 182 M, 205 M, 205 S	PS - 29
<b>TLF 6522 F9</b> 9 pinos	TC 182 N, 205 N, 206 A, 206 B, 207, 208 M, 211 M	PS - 30
<b>KFT 3AB 054F</b>	TC 20G9 (DUPLICIDADE)	PS - 31
<b>KFT 2AB 073F</b>	14G7 / PVM 1327 / PVM 1347	PS - 32
<b>KFT 3AB 074F1</b>	CTV31 L4 / 21 G7 TV+VCR DUETO , PVM 2047	PS - 33
<b>ZTFN 05004A</b>	29"	PS - 34
<b>KFT 2AA 425F</b>		PS - 35
<b>KFT 2AA 427F</b>	TC 14 A 12	PS - 36

9/22

<b>KFT 3AA 426F</b>	TC 20A12 (TRIPLICIDADE)	PS - 37
<b>KFT 3AA 428F</b>	TC 20A12 (TRIPLICIDADE)	PS - 38
<b>ZTFN 32010A</b>	TC 14A12 (DUPLICIDADE)	PS - 39
<b>ZTFN 33005A</b>	TC 20-KL03 / TC 20-KM03	PS - 40
<b>TLF 14767F</b>	TV+VCR CTV 14L3	PS - 41
<b>KFT 3AB 080F</b>	TC-20A7 (DUPLICIDADE)	PS - 42
<b>KFT 3AB 138F</b>	TV+VCR PV-M2048/2058	PS - 43
<b>KFT 4AA 448F</b>	TC 29KM03 , TC 29KL03	PS - 44
<b>KFT 4AX 242 F2</b>	TC 2922LB	PS - 45
<b>KFT 4AX 242 F3</b>	TC 25P22LB	PS - 46
<b>ZTFN 82007 A</b> ZTFN 82001A	TC 20A04 , TC 21 FJ30L	PS - 47
<b>ZTFN 35011A</b> ZTFN 35007A	TC 29KL04 , TC 29FJ30L , TC 29KL05	PS - 48
<b>KFT 5AA 369F</b>	33" TC 32SX31 E	PS - 49
<b>KFT 5AB 106F</b>	TC 33ZB , TC 33V8	PS - 50
<b>KFT 6AB 056F</b>	TC 36G32	PS - 51

## PANASONIC

<b>KF 4867 C</b>		PS - 52
<b>ZTFN 81001A</b>	TC- 14A04 20FJ30	PS - 53
<b>ZTFP 12504A</b>	TC 20RM12L / TC20RM10L	PS - 54
<b>ZTFP 12506A</b>	TC 14RM10L	PS - 55
<b>ZTFP 12507A</b>		PS - 56
<b>ZTFP 14504A</b> <b>BSC 29-0195K</b>	<b>TC - 29FX30L / 29Z99L</b>	<b>PS - 57</b>

## PAXAN / PEKONIC / PRECISION / BRASSONIC

<b>E 1051</b>	PAXAN - 14 AV 49 B	PX - 01
---------------	--------------------	---------

<b>DCF 2077</b> DDF 9802A KFS	PRECISION - PVM 2051 BR (Vide Equivalente CCE-28, Philco - PC - 07, Telefunken - TF - 03)	PX - 03 - 28 PC
<b>TCG 30 B 02</b> TCG 30 B 13	PEKONIC - CT 1000	PX - 04
<b>TCV 50 B 01</b> FCV 1422L01	PEKONIC - CT 1400, 1409 (Vide Equivalente JVC - GT-16)	PX - 05 GT-16
<b>KFS 61269</b>	PRECISION	PX - 06
<b>DDF 98020A</b>	21 M49	PX - 07
<b>KFS 61262</b>	PAXAN - 21 M49B ( Vide Eq. Cinerall - CN-06 )	PX - 08 CN - 06
<b>JF 0503</b> 122-5020503	PRECISION - PTV 2085 RNC	PX - 09

### PHILCO

<b>BW 00103</b> ( 3210-79093-00-0 )	PCS 2952 ( Obs: EM ALGUNS CASOS SERVE P/ PCS 2700 )	PC - 01
<b>FCM 14 B 007B</b> 3213009	PVT 1400 / 1410 / 1412 / 2014	PC - 02
<b>FCK 14 B 025A</b>	DUETO PVT 1418	PC - 03
<b>154 - 177 J</b>	14C82RC, CPT 2030R, CPT 1430, 2030, 2040, 2130, 2040R PAVM 2140 ( ARGENTINO ) ( Vide Eq. Goldstar - GD-02/Gradiente GT-02/LG-02/Samsung SS-06 )	PC - 04 GD - 02 GT -
<b>154 - 279</b> F 154 -	PCS 2950	PC - 05
<b>FCM 20 B 043</b>	PVT 2014, PTVR 2400 , 2410	PC - 06
<b>DCF 2077</b> DDF 9802A KFS	C141 1 R,C141 1T,CL141 1,CL141 1 R,CP141 1 R,CP141 1T,CP201 1, CP2011 R,CP2011T (Vide Equivalente CCE-28,Paxan e Precision - PX-03,Telefunken - TF-03)	PC - 07 CCE - 28 PX - 03 / TF-03
<b>OV 2094 / D1</b> <b>10 PINOS (08381 FT)</b> ( 3210-87879-01 B ) ( 3210-E2237-01-4 )	PCM 1448, 1451, 1456, 2048, 2051, 2056 PCR 1447, 1449, 2047, 2049 PCS 2050, 2060 SV-1414 2020 TP-1452N / 1453S / 1454 / 2053S / 2054 / TP-1452N CHASSIS CPH-061 CHASSIS CPH-06M	PC - 08
<b>OV 2094 / D1 - I</b> OV2094 / D1 -B	TP-2053 TP-2054 / TP-2054 EVB / PCM 2051 / TP-2052NTPS 2062N / TPS 2063 / TPS2064	PC - 09

OV2094 / D1 -C - F

OV2094 / D1-H / -I /

-N **10 PINOS**

**08381 FT**

	PAVM 2920	PC - 15
<b>3210-61313-001</b> OV 2094 / D3	PCK 1444 HI VISION	PC - 16

10/22

### PHILCO

<b>3210-61315-001</b> OV 2094 / D3	PCM 2043,PCM2046, PCS 2168	PC - 17
<b>3210-61317-00-04</b> ( CHASSIS-CPH-05 )	PCS 2700 (Em alguns casos usar BW00103)	PC - 18
<b>B 32 - 3409 B</b>	CTH - 001 (16 e 20 Polegadas) PC 1401, 1402, 1403, 1601, 1602, 1603, 2001, 2002, 2003	PC - 19
<b>B 32 - 3412 - 002 B 32-3431</b>	PC 1405, 1406, 1416, 1421, 1425 U, 1426 U, 1427U , PAVM 2140 PC 1428 U, 1603, 1605, 1606, 1613, 1616 , PAVM 2140V/ST	PC - 20
<b>B 32 - 3413 - 002 B 3210-61297-00-3 (T2) TVC / 23</b>	PC 2004, 2007, 2008, 2013, 2015, 2016 U, 2017 PC 2018, 2025 U, 2026, 2027 U, 2028U , 2040U PAVM 2040 (DUPLICIDADE), PAVM 2140	PC - 21
<b>B 32 - 3415 - 004</b>	PB 17 A 2, 20 A 2 (Filamento 6V)	PC - 22

<b>B 32 - 3427</b>	PAVM 2400U , 2040 (DUPLICIDADE)	PC - 24
<b>B 32 - 3437 - 001</b>	PC 1435, 1436 , CHASSIS 03	PC - 25
<b>B 32 - 3438 - 001</b>	PC 2035, 2036, 20 R 36	PC - 26
<b>B 32 - 3439 - 001</b>	PC 2136, PAVM 2160	PC - 27
<b>B 32 - 3448 - 003</b>	PC 1437, 1438, 1439, 1441, 1442 , CHASSIS 04	PC - 28
<b>B 32 - 3449 - 003</b> 154 - 177 W / TCAM62162	PC 2037, 2038, 2039, 2041, 2042, 2138, 2142, 20 R, 20 R 37 20R38, 20R42, PAVM 2141, 2142, 2162, 2164, 2166, CPH04, 20R48	PC - 29
<b>B 32 - 3452</b>	<b>&amp; PB 17 A 2 (Filamento 11 V) (LER MANUAL)</b>	PC - 30
<b>B 32 - 3453 - 001</b>	CPH05 PC 1443, 1444, PC 1445, PCM 1446	PC - 31
<b>B 32 - 3454 - 001</b> 1.35.52113-00	CPH05 PCM 2043, 2044, 2045, 2046, 2144,2145, 2146, PCS 2168	PC - 32
<b>6174Z - 6012 F</b> FFA97017L 3210-94714-010	PCS 2956 P / 3320 , PCS 2958 P / 3322 / PCS 2976 ( DUPLICIDADE ) ( Vide equivalente LG-13 )	PC - 33 LG - 13
<b>A 6194 - 010</b> JF0501 - 2156 3210- A6194-010 ( FFA 99057	PCS 2976, PC-A6174 (DUPLICIDADE) PCS 2956 , PCS 2979	PC - 34
<b>FFA 65025 L (1)</b> <b>OH08A</b> <b>4J</b> <b>4LXXX</b> <b>X</b>	<b>LER MANUAL</b>  PCS 2902, PCS 2802/56	PC - 35
FFA 65025 L (1) 0K0102 S 0K1707 S	TPF 2901 / V , TPF 2902 / V , TPF 3201 / V , TPF 3211 , 3221 & TPF 3421	
FFA 65025 D		
3210-A4660-01-3 LER MANUAL (CUIDADO)		
FFA 65025 L (1)OH09B1 J OH0905J		
<b>FFA 65025L (1)</b> OG36A 1 J OG36A	<b>É DIFERENTE CUIDADO!!!! NÃO DISPONÍVEL</b>	NÃO <b>DISPONÍVEL</b>
<b>FFA 97017 L (1)</b> (DUPLICIDAD E) OA20A3J	PCS 2956 N / 2902 N (DUPLICIDADE)	PC - 36

### PHILCO

<b>FFA 97035 L</b> 3210.A4941.01 -9 3210.A4941.02 7	TPF 2901 N / 2902N (DUPLICIDADE) / 2921 / 2922 PCS 2956N / 3320N / 3320V / 3322N / 3322V DVS 340DW	PC - 38
<b>FTE - 09A008</b>	PCR 1048	PC - 40

3210009		
<b>2437094</b> 3208.6141.2007.16.97.1	PCS 3300N , 3302N	PC - 41
<b>OV 2094 / D1 - A</b> 11 PINOS 08292FT---		PC - 43
<b>OV 2094 / D1 - A</b> OV 2094 / D1 -D OV 2094 / D1 -G/ -M11 PINOS 08292FT----		PC - 43
<b>FFA 65025 L</b> 3210.97177.016	LER MANUAL	PC - 46
<b>OV 2094 / D1</b> 10 PINOS 08273FT --- 08381 FT---		PC - 47
<b>OV 2094 / D1 - A</b> OV2094/ D1-B OV2094/ D1-C OV2094/ D1-D / -F /- GH /-I /-M /-N /-L /-O 08272FT--- 08273FT — 08381	TP - 2051	PC - 48
<b>OV 2094 / D1 - L</b> 11 PINOS		PC - 58
<b>JF 0501 - 19277</b> 3210-F4118-01-09	PCS 2976 / 2976S / 2978 / 2996S / TPF 2922 / 2121 <b>PUT - 2150(+ DVD) / PCS 29C21 / TPF2940 (DUPLICIDADE)</b>	PC - 60
<b>2437428</b> QH 15L		PC - 61
<b>JF 0501 - 19192A</b> 3210G0940018	TP 2054 / TP 1454	PC - 63
<b>B3210-61306-010</b>	PC 20R43, PAVM 2166	PC - 64
<b>FEA 737</b>	DSV 34" C/ PIP	PC - 65
<b>FSV 20B018</b>	PVT 2018, 2028	PC-66/ SS-41
<b>J F0501 - 19321</b>	TP 1410 /2130/2140	PC - 67/ GT-

PHILCO

<b>JF0501 - 19323</b>	TPF 2130	PC - 68
<b>FFA 99062M</b>		PC - 69
<b>FFA 65035L</b> ( DUPLICIDADE )	DVS 340 DW / DVS 346 WDE	PC - 70
<b>1142-5094</b> <b>JF0501 - 19192A</b>	TP20V56 / <b>TP 14U 56 / 14U 56B</b>	PC - 71
<b>2435371</b>	PVAM 2900	PC - 72
<b>FUH 30A006</b>	<b>TPF 2941</b>	<b>PC - 73</b>
<b>BW 00101</b> ( 4806-140-170-42 ) ( 4822-140-10506 ) ( 4822-	29GX 1892 / 1895 / 1898	PH - 01
<b>13620004A</b> ( 4806-140-170-91 )	38" <b>CUIDADO ≠ 4806.440.170.91</b> 28PD6921 <b>TV + DVD</b>	PH - 02
<b>140 - 170 - 77</b> 4806-140-170-77 ( 4936	29 PT 752 A	PH - 03
<b>OV 2076</b>	20 GL 1333	PH - 04
<b>OV 2076 ( 20591 )</b>	33 PT 772A	PH - 05
<b>OV 2076 ( 20592 )</b> ( 4806-140-170-78 )	29 PT 652 A 29 PT 662A, 33 PT 772 A	PH - 06

**OV 2076 ( 20593 )**  
( 4806-140-170-85 )

29 PT 632, 634, 634A, 634, 634A  
33 PT 752, 33 PT 772, 33 PT 854

PH - 07

**OV 2076 ( 20601 )**

( 4806-140-170-72 )	29 PT 552A / 78R	PH - 08
<b>OV 2076 ( 20692 )</b> ( 4806-140-10672 )	33 PT 574	PH - 10
<b>OV 2076 ( 20732 )</b>		PH - 11
<b>OV 2076 ( 20905 )</b>		PH - 12
<b>OV 2076 / -</b> <b>A</b> OV2076 / <b>- B</b> OV2076 OV2076/ - D / - F / - G - L / - M / - N / - O / - H / - I <b>21421 FT—</b> <b>( 4806-140-170-89 )</b>	29 PT 658A / 78R 33 PT 578 29 PT 658 , 33 PT 578	PH - 13
<b>OV 2076 / B2</b> OV2076 / B2 -C OV2076 / B2 -L / -O <b>08021 FT—</b> <b>( 4806-158-870-59 )</b>	PT 554	PH - 15
<b>OV 2076 / B3</b> 4806-140-17039 3128-138-21041	20 PT 656 A , 29 PT 856 A	PH - 18
<b>OV 2076 / B3 - B</b> OV 2076 / B3 - A OV2076 / B3 - D / -F H /-I /-M /-N / - O		PH - 19
<b>AT 2077/ SO / 50</b> AT 2077/ 1° VERSÃO ( 4806-140-170-31 ) ( 4806-140-170-47 )	28 GR 7580, 28 GR 7680	PH - 36

## PHILIPS/MAGNAVOX

AT 2077/ 2° VERSÃO ( 3832-0 ) <del>( 4806-140-170-24 )</del>	28 GR 7585, 7685 V 9350-BP 21 GR 7560 <b>(CUIDADO DUPLICIDADE)</b>	PH - 37
<b>AT 2078 ( 21151 )</b> 4806-140-170-87	29 PT 836 , 29 PT 368 21 PT 836	PH - 39
<b>AT 2078 / - A /</b> AT 2078 / - B AT 2078 / -C AT 2078 / -D / -F / -G H /-I /- M /- N /- O /-L <b>21391 FT—</b> <b>21401 FT—</b> <b>( 4806-140-170-88 )</b> <b>3128-138-2115</b>	21 PT 838A 29PT4631 / 29PT4831 BR (DUPLICIDADE) 29 PT 458 / 558 (DUPLICIDADE) PT 838A PT 848 29 MT 4505, MAGNAVOX <b>21 PT 8364/78R</b>	PH - 40
<b>AT 2078 / - B</b> 21321 FT—	(DUPLICIDADE)	PH - 42
<b>AT 2078 / B 1</b> ( 4806-140-170-63 )	25 GX 1889, PT 230	PH - 43
<b>AT 2078 / B 2</b> AT 2078 ( 20311 ) ( 4806-140-170-68 ) ( 4822-140-106-37 )	21 PT 230, 21 PT 232 21 PT 1663, 21 PT 2682, 21 PT 4404, 21 PT 4424 PT 212 , PT 240	PH - 44
<b>AT 2078 / B4</b> ( 4806-148-870-57 )	PT 534	PH - 45
<b>AT 2078 / B4 - F</b> AT 2078 / B4 - N		PH - 46
<b>AT 2078 / S O</b> 3760 - 3 SR047.5 ( 4806-140-170-51 ) ( 4806-140-170-75 ) ( 4806-148-870-21 )	14 GL 1010 , 1310 , 1410 16 GL 1030 , 1330 20 GL 1040 , 1340, 1440 CHASSI GR1 -AL	PH - 55
<b>AT 2079 / B O</b>	14 GL 1013, 1014, 1313, 1314, 1315	PH - 56



U 9252 UV 9239/49 (4806-140-170- )	20 GL 1044, 1343, 1344, 1345 1043,	
<b>AT 2079 / B</b> (4806-140-170- ) <del>(4806.140.170-</del>	17 BL 2022	PH - 58
<b>AT 2079 / B</b> (4806-140-170- )	14 GX 1616, 1618	PH - 59
<b>AT 2079 / B</b> (4806-140-170- ) (4806-140-170- )	20 GX /56/58/60 21 GX 1665, 1666, 1668	PH - 60
<b>AT 2079 / B</b> (4806-140-170- )	14 GL 14 GL	PH - 61
<b>AT 2079 / B</b> (4806-140-170- )	& 20 GL 20 GL (LER MANUAL)	PH - 62
<b>AT 2079 / B</b> (4806-140-170- )		PH - 63

### PHILIPS/MAGNAVOX

<b>AT 2079 / B 9</b> (4806-140-170-59 ) (4806-140-170-66 ) (4806-140-170-81 )	20 GL 1048 , 21 GL 1369 20 GL 1049 20 GL 1349 21 GL 1639	PH - 64
<b>AT 2079 / B 10</b> (4806-140-170-61 )	14 GX 1619	PH - 65
<b>AT 2079 / B 11</b> (4806-140-170-62 )	14 GX 1619 20 GX 1659 21 GX 1669	PH - 66
<b>AT 2079 / B 12</b> (4806-140-170-58 )	14 GL 1018 14 GL 1019, 1319	PH - 67
<b>AT 2079 / S</b> AT 2079 / SO SR-143-3 SR-149-6 SR-2044 SR-3842-4 SR-3842-3 (3265-1 ) (3842-4 ) (4806-140-170-29 ) (4806-140-170-76 )	14 GL 1011, 1012, 1031, 1032, 1311, 1312, 1411, 1420 16 GL 1031, 1032, 1331, 1332 20 GL 1041, 1042, 1341, 1342, 1441 21 GL 1451, 1452	PH - 68
<b>OV 2094 (20662)</b> OV 2094 (20661)	PT 316	PH - 69
<b>OV 2094 / 31-8</b>		PH - 70
<b>OV 2094 / 41</b> (4806-140-170-67 ) (4806-140-170-73 ) <b>4822.140.10612</b>	14 PT 100G/78,14 PT 110A,14 PT 111A,14 PT 112 A,14 PT 113 A, 14 PT 210 A, 20 PT 120A, 20 PT 121A, 20 PT 122 A, 20 PT 123A, 20 PT 220 A / 230A	PH - 71
<b>OV 2094 / 42</b> (4806-140-170-69 ) (4806-140-170-74 )	14 PT 212A, 17 PT 1511/1563 , 20 PT 222A, PT 324 20 PT 2682, 21 PT 232A	PH - 72
<b>OV 2094 / -A</b> OV 2094 / -B OV 2094 / -C OV 2094 / -D / - F / - G - H / - I / - L / -M / -N / - <b>10 PINOS</b> <b>08301FT—</b> <b>20662FT—</b> <b>21541FT—</b> (4806-140-170-90 ) (4806-140-170-99 )	14 PT 418 / 20 PT 218 / 20 PT 228 / 78R / 20 PT 428 20 PT 529A / 78R / 20 PT 5290	PH - 73
<b>OV 2094 / AO - A</b> OV 2094 / AO - B OV 2094 / AO - C D / -F / -G / -H / -I / -L M / -N / -O <b>08231 FT...</b>		PH - 74
<b>OV 2094 / B1</b> (4806-148-870-56 )	PT 314 / 414, 20 PT 326 A / 78 , 20 PT 424, 20 PT 324, 14 PT 316 , 20 PT 524	PH - 84
<b>OV 2094 / B1 - 1</b>		PH - 85

## PHILIPS/MAGNAVOX

<b>OV 2094 / B1 -</b> AOV 2094 / B1 -BOV 2094 / B1 -C OV 2094 / B1 -D / -F / -G / -H / -I / -M / -N / <b>20661FT—</b> <b>20662FT—</b> <b>(4806-148-870-56)</b>	14 PT 616 A / 20 PT 324 / 20 PT 424A / 78 <b>14PT618A/78</b>	PH - 87
<b>OV 2094 / -</b> OV 2094 / - B OV 2094 / - C / - D / - OV 2094 / - G / - H / - I L / - M / - N / - O 11 PINOS 08231FT— <b>08361FT—</b>	(DUPLICIDADE)	PH - 91
<b>2 4 3 7 2 0</b> (4806-140-170-52)	25 GX 1888, 29 GX 1888	PH - 100
<b>(4806-140-170-</b> 3121-218-30121 EIA 232	29 GX 1899, 1999	PH - 101
<b>4822-140-10609</b> (4822-140- 10609) AT 2079/B13 OV 2094/50	14 PV 162. 14 PV 163. 14PV 172 PV 461 / 471 20PV471/78 CANGURU	PH - 102
<b>5 3 1 - 0 2 2 -</b> 531-022-79	29 PT 762 A	PH - 103
<b>CTO - L / CTO - C</b> (4806-140-170-22) (4806-140-170- 25) (4806-140-170-56) <b>37321</b> <b>SR - 041</b>	& (LER MANUAL) 21 CT 7675, 21 CT 7678, 28 CT 7690, 28 CT 7692 28 CT 7693, 28 CT 7694 21 CT 7470 CHASSIS CTO - C	PH - 104
<b>CTO - 9 (PINOS)</b> (4806-140-170-23)	& (LER MANUAL) 14 CT 6401 , 16 CT 6010 , 20 CT 6035 CHASSIS CTO - 9	PH - 105
<b>NCF - 10 (PINOS)</b> (4806-140-170- 22) <b>37141</b> <b>SR - 935</b>	16 CN 4435 , 16 CN 4416 , 16 CN 4066 CHASSIS NCF - 10	PH - 106
<b>OV 2076</b> 3128.138.20593 (2 FOCUS)	34" 34PT8419	PH - 108
<b>JF 0 5 0 1 -</b>	14 PT 3131 , 20 PT 3331, 20 MT 3331 / <b>21 MT 2136</b>	PH - 109
<b>JF05 01-1 91</b>	PT 639 / 739 / 21 PT 5431	PH - 110
<b>4806-140-</b> 3832-2	21 GR 7560 <b>(CUIDADO DUPLICIDADE)</b>	PH - 111
<b>JF 0501-1215</b>		PH - 112
<b>OV 2094/ B1-8</b>		PH - 114
<b>AT 2078 / B4-2</b>		PH - 116
<b>1 1 4 2 . 5 0 2</b> 4822.140.10525	14 GX 3516, 14 GX 8510, 20 GX 8550	PH - 118
<b>AT 2078 / B4-2</b>		PH - 116
<b>1 1 4 2 . 5 0 2</b> 4822.140.10525	14 GX 3516, 14 GX 8510, 20 GX 8550	PH - 118

## PHILIPS/MAGNAVOX

<b>OV 2094 / A1 -</b> AOV 2094 / A1 - C		PH - 137
<b>OV 2094 (08292)</b>		PH - 139
<b>JF 0 5 0 1 -</b> <b>2 1 3 5</b>	21 PT5431/5432, 25 PT 5531, 29 PT 4631 (DUPLICIDADE), 29PT 4640 , 21 HT5432 , 29HT4631, 25 PT 5541	PH - 140



<b>OV 2094 / - A</b> (10PINOS) OV2094-1 (08301 FT) OV 2094 (08301)		PH - 147 CN - 16
<b>OV 2094 / A1</b>		PH - 148
<b>AT 2078 / - A</b> AT 2078 / - C AT 2078 / - D AT 2078 / - F /-G / -H /-I /-L /-M /- N / - O 21321 FT---		PH - 149
<b>OV 2094 / A1 -</b> <b>B</b> OV 2094 / A1 - A OV 2094 / A1 - C  OV 2094 / A1 -D /-F /-G H /- I /- L / -M / -N / - O 08351 FT---		PH - 159
<b>AT 2078 / B4 - D</b> <b>AT 2078 / B4 - M</b> <b>AT 2078 / B4 -</b> <b>O</b> <b>3128.138.206</b>	21 PT 534 / 78R	PH - 168
<b>AT 2078 / - H</b> AT 2078 / - C AT 2078 / - D /- O 21341 FT---		PH - 171
<b>AT 2078 / - D</b> <b>AT 2078 / - A</b> <b>AT 2078 / - B</b> <b>AT 2078 / - C</b> <b>AT 2078 / - H</b> <b>AT 2078 / - M</b> 21342FT---- 3.128.138.213. 42	28PW6421 / 6431	PH - 173
<b>OV 2076 / AO</b>		PH - 174
<b>JF 0501-21835</b>	34 PT 8419 / 78 (DUPLICIDADE) / <b>29 PT 4641</b>	PH - 175

**PHILIPS**

<b>JF 0501-19272</b> 2422.531.026.13	21 PT5433 / 21 PT 5435, 21 PT 5437, <b>21 PT6456</b>	PH - 176
<b>JF 0501-21133</b>	29 PT 5642 (DUPLICIDADE) / 28 PW 6441/78	PH - 177
<b>JF 0501-2136</b> <b>2422.531.024-72</b>	29 PT 5632 , 29 PT 5642 (DUPLICIDADE), PT <b>5645,29PT6566</b>	PH - 178
<b>OV 2076 / - A</b> OV 2076 / -B OV 2076 / - C OV 2076 / - D / -F / -G H / -L / -M <b>21362FT----</b>		PH - 180
<b>OV 2076 / - A</b> OV 2076 / - B OV 2076 / - C OV 2076 / - D / -F / -G  H / -I / -L / -M / - N / -O 21921 FT---	28PW6532	PH - 181

OV 2094 / - A OV 2094 / - B OV 2094 / - C OV 2094 / - D / - F / -GH / -I / - L / -M / -N / -O 082F4 FT—		
<b>PWL13 - B</b> PWL 13 - A PWL 13 - G / -I PWL 13 - N / - <b>O08411</b> <b>FT—</b>	20PT 3331 / 20PT 4331 PT 3496	PH - 210
<b>PWL 13 - C</b> PWL 13 - D PWL 13 - H / - M <b>08412FT—</b>	20 MT 3331 MAGNAVOX	PH - 211
<b>OV 2076 / B2 - I</b>	29 PT 554A / 78	PH - 219
<b>KF 58383P</b> 4822.140.10469	29 SX 8674 / 29 SX 8878/79 29 PT 758 / 78	PH - 220 MT -22
<b>AT2078 / 21391 FT</b>	29 PT 338	PH - 221
<b>1142.5093D</b> 2422.531.02323	14 PT 519 20 PT 529	PH - 222
<b>JF 0501-8604</b> 2422.531.00047	29PT4131 / 29MT 4515/78 MAGNAVOX/ 29PT 4635 / 29PT4640 29PT 4643 / 29PT4647	PH - 223
<b>PWL - 15</b> 34111		PH - 226 CN-14
<b>3104 308 20831</b> 13929004G	36PW8521 36PW9818	PH - 229
<b>8228.001.3476.1</b>		PH - 230

## PHILIPS

<b>OV 2076</b> 4806.140.170 -8421041 21041 FT—	37PT 786/78 <b>37 PT / 782A /78</b>	PH - 231
<b>JF 0501-19865</b> 2422.531.00114	14PT3336 20PT3336	PH - 232
<b>JF 0101 - 85038</b> 2422.531.00067	<b>TELA PLANA</b> 32PW8422	PH - 235
<b>JF 0101 - 85040</b> 2422.531.00069	29PT8422, 34PT8422	PH - 236
<b>13620004C</b> 2422.531.98025	28PW6521, 28PW6816 , 32PW878A , 32PW6521 28PW858	PH - 241
<b>4806.440.170.91</b> 00.368.026-0001 3.121.218.301.81	33PT670 <b>CUIDADO # 4806.140.170.91</b>	PH - 244
<b>JF 0101 - 85021</b>	32 PW6542 / 28 PW6542	PH - 245
<b>JF 0501 - 19973</b> 6174V - 6016B		PH - 246
<b>JF 0501 - 19991</b> 6174V - 6016A		PH - 247
<b>BSC23-3369L</b> <b>6174Z-14001A</b>		PH - 248
<b>BSC29-3807D / F/</b> <b>9965.100.04931</b> <b>9965.100.13783</b> <b>FQH21A0049965.100.09</b>	21 PT9467C <b>(DUPLICIDADE)</b> <b>21 PT9467</b>	PH - 249
<b>JF0501-3297</b>		<b>PH - 251</b>
<b>OV 2094 / - A</b> OV 2094 / - B OV 2094 / - C / - D / - OV 2094 / - G / - H / - L / - M / - N / - O <b>11 PINOS</b> 08292FT—		PH - 255
<b>OV2076/21461</b>		PH - 256

<b>OV20/621972</b> <b>4806-140-17039</b> 3128-138-21041		PH- 257 PH- 258
<b>BSC 29-0134Z</b> <b>9965.1000.19373</b>	<b>29 PT 9467S/78 ( DUPLICIDADE)</b>	<b>PH - 259</b>
<b>BSC 29-0135Z</b> <b>9965.1000.13187</b>	<b>29 PT 9467C</b> <b>29PT8467S (DUPLICIDADE)</b>	<b>PH - 260</b>

<b>BSC 29-0167H</b>	<b>29 PT 9467S</b>	<b>PH - 261</b>
<b>BSC 28-N2392</b> <b>(9965.1000.19510)</b>	<b>29 PT 8568 C</b>	<b>PH - 262</b>
<b>242.253.100.152</b>	<b>29 PT9457/78</b>	<b>PH - 263</b>
<b>BSC 25-N1571</b>		<b>PH - 264</b>

**R C A, GE, ROADSTAR**

<b>154-387 B</b>	RBA 2020	RCA - 01
<b>FCV 2010E10</b>	TVC - 20	RCA - 02
<b>2 G 25026</b> (316 / B1 G / B2F)	RCA - CTC 186 A, F 20637N, F 20638N, F 29632N GE - 25G542	RCA - 03
<b>T4401-1</b> <b>HVT T</b> 4401 - 1 <b>HVT</b>	RCA 2700X1 / RCA 29520BE1- UX1 / RCA 33683UX1 / RCA 37683UX1 AS 20200FBL	
<b>JF 0501-1901</b> DCF 980702-BC	ROADSTAR - K 9780	RCA - 05
<b>PN 2G 25027</b> 2G25027-A3D	RCA - RBA 29551	RCA - 06
<b>JF 0208 - 0208C</b>	ROADSTAR - K-9730	RCA - 07
<b>FCV 201 0E09A</b> 230934	RCA - RBA 1420	RCA - 08 GT - 06

**SAMSUNG , SEMIVOX**

<b>FCM 1411 L 01</b> FCM 1415 AL TLF	CB 336F CN 3313 Z, 3315, 3315 Z, 3316, 3329 Z, 3352Z, 3355 Z, 3357 3361, 3552 Z, 5029 Z, CB 336F	SS - 01
<b>FC 1412</b>	TS - 14C1 R ( Vide Equivalente First Line - KY-01 )	SS - 02 / KY - 04
<b>FCK 14 A 022</b>	SEMIVOX	SS - 03
<b>FCK 14 A 028</b>	SEMIVOX ( Vide Equivalente Baysonic - BY - 01 )	SS - 04 / BY - 04
<b>FCK 14 A 033</b>	TV SAMSUNG CN 3338V / 3339 VB - CINAL	SS - 05
<b>154-177 J</b>	MAT 5352 E (Vide Eq.Gradient - GT-02/ Goldstar - GD-02 / LG-02 / Philco-PC-04)	SS - 06 GT - 02 G D -
<b>154-375 A</b>	( Vide equivalente Goldstar - GD-05, Gradiente - GT-04, LG-04 )	SS - 07 GD - 05 GT - 04
<b>154-375C</b>	( Vide equivalente Goldstar - GD-06, LG-05 )	SS - 08 GD - 06 / LG -
<b>FSV 20 A 001</b> AA26- 30004H FCV44A	CN 331, 501, CN 3348, 5038, 5039, 5048, 5066	SS - 09
<b>FSV 20 A 001 / 27</b>	TXB 2535 / 2735	SS - 10
<b>FCG 2045 AL</b>	20 CB 534 V / 563Z , CN 5322 CN 5029, 5029 V, 5029 W	SS - 11
<b>FCM 20 A 015</b>	CN 5062, 5062 V, 5062 W CN 5083, 5083 V, 5083 W CN 5314, 5314 V, 5314 W	SS - 12
<b>FCM 20 A 023</b>	CN 5055 Z / CN 5050 / CN 5052, CN 5062 Z	SS - 13
<b>FSV 20 B 012</b>	( Vide Equivalente Cinal - CN-03 )	SS - 14 / CN - 06
<b>FCM 20 B 057</b>	SEMIVOX - TS 14C2R , TS 20C2R	SS - 15
<b>FCM 2014 FL</b>	CN 3329 V, 3338 V, 3362 V, 3383V , HPS 14 (CCE), CN 3355 Z	SS - 16
<b>FCM 2015 CL</b> TLF 70018A	( Vide Equivalente CCE-27)	SS - 17 CCE - 27
<b>FCM 2015 ML</b> FA2040 KFS 60769 AA26-30001C	CN 5013 Z	SS - 18
<b>FA 2017</b>	TS - 20C1 R ( Vide Equivalente First Line - KY-03 )	SS - 19 / KY - 03
<b>FTH 29 A 001</b>	CN 7202 WB, CN 7207, CN 723	SS - 20
<b>FTR 29 A 003</b> AA26-30002B	CN 7266	SS - 21

<b>FCZ 29 A 006 A</b>	29 CN 721	SS - 22
<b>FTH 29 A 013 S / P</b> FTK 14 R 005 C	SAMSUNG - 14" e 20"	SS - 23
<b>FTH 29 A 013 S / G</b>	29 CN 765 / <b>29 CN765 DWX</b>	SS - 24

<b>FCR 29 A 014 R</b>	CN 7226 W, CN 7230	SS - 25
<b>FTK 20A007P</b>	TV + VCR CANGURU MVR-4190M	SS - 26
<b>FCR 25A006R</b>	SAMSUNG - TXB 2525 / TXC 2516 / CN 2516	SS - 28
<b>FD 2139 ( DNF )</b>	SEMIVOX - (JKR) TS-25C15	SS - 29
<b>FUH 29M002</b>	SAMSUNG - 21 M29 MQ/ CL34V6PQ , CN34V6PQ , CL34Z6PQ	SS - 30
<b>FFA 61012K</b> FFA 61012L	SAMSUNG CL 29MZIMQ	SS - 31

**SAMSUNG , SEMIVOX**

<b>FUH 29A001 F</b>	SAMSUNG CL 29M21	SS - 32
<b>FSV 20B001</b>	SAMSUNG	SS - 33
<b>FUH 29A001 G</b>	SAMSUNG CL 29K40MG / <b>CL29K40MQ</b>	SS - 34
<b>FOK 14B001</b>	SAMSUNG - CL21M21 , <b>21N11M119</b>	SS - 35
<b>FUH 29V003</b>	SAMSUNG	SS - 36
<b>FCA 173 / AA26-</b>	SAMSUNG - CL21 M6MQ, CL 21K40	SS - 37
<b>FQH 21A001</b>	SAMSUNG	SS - 38
<b>FUH 29A001 V</b>	SAMSUNG	SS - 39
<b>FCK 1415EL</b>	SAMSUNG - DX 1332, TTB 1340	SS - 40
<b>FSV 20B018</b> 3220045	SAMSUNG	SS - 41
<b>FUH 29V006</b>	SAMSUNG - CL32Z 30DS	SS - 42
<b>FUH 29V001</b>	SAMSUNG CL 32Z30DS	SS - 43
<b>FUH 29V007B</b>	SAMSUNG - RETRO	SS - 44
<b>FCK 1415AL</b>	SAMSUNG - M3105	SS - 45
<b>FCM 20A025</b>	SAMSUNG - CXB 1922	SS - 46
<b>FCR 25A001</b>	SAMSUNG - 25 CN 6229W	SS - 47
<b>FOK 14A001</b> AA26-00231A	SAMSUNG	SS - 48
<b>FSV - 14A004 H(S)</b>	SAMSUNG	SS - 49
<b>JF0501-91910A/B</b>	CL 21Z43MQ <b>SLIM</b>	SS - 50
<b>FUH 32V001B</b>	SAMSUNG	SS - 51
<b>FUH 29A003</b>	SAMSUNG - CL 29Z43 <b>SLIM</b>	SS - 52
<b>JF0501-91911</b>	<b>CL 21Z43MQ</b>	<b>SS - 53</b>
<b>FQH 21A002</b>		<b>SS - 54</b>
<b>FQH 21A003</b>		<b>SS - 55</b>
<b>FQH 21A004</b>	<b>CL 21Z43MQ</b>	<b>SS - 56</b>
<b>FQH 29A003</b>	<b>CL 29Z43</b>	<b>SS - 57</b>
<b>FQH 21S001</b>		<b>SS - 58</b>
<b>BSC 25-0217G</b>	<b>CL 21Z58MQ</b>	<b>SS - 59</b>
<b>FDA 006 N</b>	CTP 3765, 3766	SY - 01
<b>FDA 007 N</b>	CTP 6765 V, 6766 V	SY - 02
<b>FD 0059</b> AC 30050	CTP 3750, 3751, 3752, 3755, 4751	SY - 03
<b>FD 0060</b> AC 30051	CTP 6750, 6751, 6752, 6753, 6755, 6755V-D4KM	SY - 04
<b>FD 0108</b> AC 30052	CTP 3756-V-00	SY - 05
<b>FD 0109</b> AC 30053	CTP 6756-V-01	SY - 06
<b>FD 0181</b>	CLP 2128, CLP 2127	SY - 07
<b>F 1175 - 76</b>	CTP 3720, 3721, 3722, 6720, 6721, 6722	SY - 08
<b>FD 125</b>	CTP 3770, 3771, 3780, 3781 CLP 1451	SY - 09
<b>FD 187</b> L 40 B 03900	CTP 6050, 6051, 6770, 6771, 6780, 6781 CLP 2151	SY - 10
<b>L 40 A 00100</b>	CTP 3790, 3791 , 3792	SY - 11
<b>L 40 A 00700</b> L 40 A 00710 L 40 A 00711	C 29 LH 43 B , 2997 C 33 LJ 43 B 00 C 3396, CP C 29L B1	SY - 12
<b>L 40 B 00300</b>		SY - 13
<b>L 40 B 02510</b>		SY - 14
<b>L 40 B 05500</b>	CTP 6790, 6791, 6792 (20polegadas), 6796	SY - 15
<b>L 40 B 05700</b>	C 2796, 2996, C 29F5 AD	SY - 16



<b>F 0017</b> F0017 MESA/MQBD	C 29 ST 54 (COM BOBINA NO FERRITE) FRST LINE 29FL10	SH - 02	86,5 0
----------------------------------	--	---------	-----------

**SHARP**

<b>F 1232</b> ( Z 4034 ) 14 "	C 1402, 1404, 1417 A, 1425, 1460, 1480, 1484	SH -
<b>F 1250</b> ( Z 4035 ) 16 "	C 1604, 1615, 1616, 1625, 1660, 1665, 1686, 1690	SH -
<b>F 1251</b> ( Z 4036 ) 21 "	C 2011, 2015, 2016, 2018, 2025, 2028, 2029, 2060 C 2086, 2090, 2181, 2186	SH -
<b>F 1562</b> ( Z 4086 )	C 1425 B, 1426 B, 1430 A, 1465 B, 1487 B, 1490 A C 1425 A	SH -
<b>F 1563</b> ( Z 4085 )	TVC 1625, 1626, 1630 A, 1665, 1687, 1690, C 2065 B	SH -
<b>F 1564</b>	C 2025, 2026, 2030, 2090 "A", 2030 A , 2065	SH -
<b>F 1693 ( Z 4183 )</b>	C 1430H,1492 H, 1626, 1630, 1631, 1665, 1690, 1694, 2035B, <b>2199,2052B</b>	SH -
<b>F 1694</b>	C 1426, 1427, 1430, 1431, 1491 B, 1410, 1410 B, 1450 B, 2065H	SH -
<b>F 1802</b>	C 2877 B, 2899 A	SH - 11
<b>F 1833</b> ( CE- 00066 )	C 3399	SH -
<b>F 1881</b> F 1890 F 1952	C 1413, 1453, 2013, 2017, 2018H, 2053, C 21ST54	SH -
<b>F 1894</b>	C 1482, C 1485, 1482 B, 1485 B	SH -
<b>F 1901( C )</b> FOCO Z 4175 154-207R/S	C 2040, 2041, 2082, 2188, 20 R 11, 20 R 12, 20 S 01 C 20 S 02, 20 T 51, 2052, 2053, 2092 B	SH -
<b>F 1923</b>	C 1413, 1440, 1440B, 1450, 1452B, 1453, 1467B, 1482B, 1485B, C 14R12, 14RS02, 14RS03, 14T51, 14S02	SH -
<b>F 1998 CE ( G )</b>	C 1453 / 1457 / 14 ST 57 / 1417 DUPLICIDADE	SH -
<b>F 2005 CE ( H )</b>	C 1438, 2038, 2057, 20 ST 57 , 20 ST 58	SH -
<b>F 2023( E )</b> 6174Z-6279X	C 29 ST 58 / 29 ST 98	SH -
<b>F 2092</b>	147 B, 1626, 1630 H, 161B, 2010, 027, 2030 H, 035, C 2095	SH -
<b>TAT 14101A</b> TAT 14101A	(Vide Equivalente CCE - 60)	SH - 21 CCE - 60

**SONY**

<b>1-439-311-32</b>	KV 1449 AV	SN - 01 SN - 02
<b>1-439-416-21</b>	KV 29 XTR 300 / TR 3	SN -
<b>1-439-416-41</b>	KV 29 XTR 20 / 30 , KV 2553 BM / MT, KV 20TS27	SN -
<b>1-439-416-61</b>	KV 2114 S, KV 2127 R, KV 2137 RS, KV 2161 S, KV 2110 GM	SN -
<b>1-439-418-31</b> 1-439-429-11	KV 2940 BMKV 2945	SN - 06
<b>1-439-421-11</b>	KV 1483	SN -
<b>1-439-421-41</b>	KV 1440 B, KV 1441 B, KV 2163S	SN -
<b>1-439-421-51</b>	16" e 20" KV 2160 B	SN -
<b>1-439-423-11</b>	KV 2102 , KV 2500, 2114, 2123 , 2133, 2134, 2153	SN -
<b>1-439-423-21</b>	KV 20EX10 , KV 29TR20 , KV 2553BM	SN - 11
<b>1-439-423-31</b>		SN -
<b>1-439-423-32</b>	KV 27 EXR 20 , KV 29XTR30	SN -
<b>1-439-423-41</b>	KV 20TS27 / KV 29XTR30	SN -
<b>1-439-423-51</b>	KV 2161 / KV 2160	SN -
<b>1-439-454-11</b>	KV 27ASR10 / iS	SN -

**SONY**

<b>1-439-455-11</b>	KV 27XBR15 / BR65	SN -
<b>1-439-498-71</b> 1-439-498-12 1-439-498-21 1-439-498-51	KV 2955, KV 2959, KV 3459, KV 27V15 , 29 V 15 STR, KV 29 V 55, KV 32 TS 35, 32XBR45, 32S10, 34 V 55 Modelos importados até o ano de 1994 c/ potenciômetro de foco, "32" 32V15	SN -
<b>1-439-520-11</b> 1-453-126-11	KV 32 XBR96S , KV 32 S 26 , KV 35 V 35 , KV 35 V 36 KV 32S36 / KV 32XBR9 / KV 32XBR96, 27X BR25	SN -
<b>1-453-141-21</b>		SN -
<b>1-453-142-11</b>	KV 2163S	SN - 21
<b>1-453-142-21</b>	KV 2160 , KY 14MTR1	SN -
<b>1-453-146-11</b> 1-453-146-21	KV 27 S 10, 27 S 15, 2959T, 29 RS 10, 2970, 32S16, 32 TS 36	SN -

<b>1-453-207-11</b>	<b>α</b> KV 2970 I, KV 32S22 , 3470, KV 3470 I, KV 32S45	SN -
1-453-238-31	NX 2609 (LER MANUAL)	
<b>154 - A 51 J</b>	KV 2DVM - 3P ( TV + VCR ) / KV 20VM20 , KV 20VM30	SN -
<b>AT 2078 / UO - 1</b> AT 2078 / UO AT 2078 / UO - 2 ( 1-453-208-11 )	KV 1450 B ( Cinesc. Samsung ), KV 2158, 2172 S KV 2170 B, KV 2173 S, KV 21 B 80 , KV 21 VH5BR KV 2159 , KV 21S85, KV 21VM5BR , KV 21VH5BR	SN -

AT 2079 / UO	& KV 1450 (Obs: Sem potenciômetro de Focus Screen)(LER MANUAL)	SN - 27
AT 2079 / U1 ( 1-453-209-11 )	KV 1450 B (SOMENTE P/ CINESCÓPIO SONY) KV 14B80 / KV 14VM5BR OBS: CASO SEJA CINESCÓPIO SAMSUNG NÃO SERVE	SN -
AT 2079 / U2 ( 1-453-216-11 ) ( 1-453-217-11 )	KV 140 MG KV 200 MG KV 205 MP	SN -
8-598-834-20 8-598-834-10	KV 29FS12, KV29FV15B, KV29V15, KV29V15B, KV29FV16B, KV 29V16B, KV29FV100,KV29FS100,KV29FA21,KV29FS12B (DUPLICIDADE) KV 29FVS1 / KV 28FS15 / KV 29FS105	SN - 31
8-598-838-40 1.453.316.11 8.598.838.41	KV 21 FE 12 B KV 21 FS100 KV 21 FS 105	SN -
8-598-850-00	KV 25 FV 10 B / KV 25 FV 12 B	SN -
8-598-922-00 ( 1-453-188-11 ) ( 8-598-938-00 )	KV 21 XTRI, KV 2152, KV 2158, KV 2159, KV 2162 , KV 2163 , KV 21 X TR II	SN -
8-598-928-01 8-598-939-00	KP 41 PT 15 B ( TELÃO ), KP 53XBR45 , KV 61 V 15	SN -
8-598-969-00	NX 2609, KV 2970 T, KV 3470, KV 3470 T , HV 2090 T	SN -
8-598-976-00	KV 29 VX 2, KTV - 33T80, KV 34T80 , KV29VY2	SN -
8-598-998-00 8-598-998-03 1-453-268-11	KV 29 T 75, KV 29 T 76 , 29T80 (NX 4005) KV 27V66 (IMPORT.) / 29 AL 40 A	SN -
8-598-828-00 /	KP53XBR200/BR300 / KP57XBR600 / KP57WV600 / KP61XBR200/ KP65XBR7 / KP 65WS510	SN -
1-453-310-11	KV 29FV16B / KV 29FV30 / KV32FV30 (DUPLICIDADE) / KV 29 FA 210 KV 29FS100 / KV 29FA21 / KV 29FS105 / KV 29FS110	SN -
1-453-338-31 1-453-338-11 1-453-338-21	KV 29FS100 / KV 32FV30 (DUPLICIDADE)	SN - 41
1-439-452-11 1-439-533-11	KV 32FV30 (DUPLICIDADE)	SN -
AT 2078 / UO - AT 2078 / UO - 08111FT--- AT 2078 / U-6 08111FT---		SN -
8-598-824-10	KV 34 FV 15 B / KV 38 FV 15 B / KV 34 FS 13 B / 32 FS 12 B	SN -
8-598-994-00	TELÃO - KP 61 V85 / KP53SV75B / KP61 SV85T / KP43T85 / KP53SV65B	SN - 45

SONY

1.439.502-11 1.439.498-31 1.439.502-31	KV 27TS27 KV 32TS53	SN - 46
1.453.524-11	KV 32FV30, KV 32XBR95	SN -
1.453.147-21 1.453.149-21		SN - 48
1.453.336-11		SN -
1.453.189-11	KP 61 XBR48 / KP 53XBR45	SN -
8.598.939-00	KP 53S15	SN - 51
1.453.267-11		SN -
1.439.456-11 1.439.457-11 1.439.457.27	KV 32XBR15 / KV 32XBR55 / KV 32XBR65	SN - 53
8.597.041-10	KV21XTRL	SN -
8.597.043-10 1.453.479.41	KV29FS140	SN - 55
8.598-858-00	KV 21 FS140	SN -
1.453.316.11		SN - 57
8.598 .871- 20 8.598	34FV310 / 38FV310	SN - 58

**TELEFUNKEN**

<b>FCV</b> <b>1410 E</b> <b>06</b>	14 C 5170 ( Vide equivalente Gradiente - GT-01 )	TF - 01 GT - 01
<b>FCV</b>	20 C 5170	TF -

( 571 391 001 902 )	( Vide equivalente Gradiente - GT-05 )	GT - 05
<b>DCF 2077</b> D D F	AV 135 (Vide Equivalente CCE-28, Paxan e Precision - PX - 03, Philco - PC - 07 )	TF - 03 CCE - 28 PX - 03
<b>pinos</b>	Chassi: CH 801, 802, 802A	TF -
<b>pinos</b>	Chassi: CH 841	TF -

**TOSHIBA**

<b>AT 2079 / AO</b> AT 2079 / A2 AT 2079 / A3 (TFB 4067) (TFB 4125 DD) (TFB 4125	TV 147, 204, 207, 209, 14 A 76 MU, 14 A 82 EAV, 147 CR TV 20 A 76 UM, 20 A 77SU, 20 A 82, 1022 EAV, 1455 , 1458 S TV 1474 AMU, 1483 AAV, 2055, 2058 S, 2066 SU, 2078 AMU TV 2079 ASU, 2083 AAV, 2175 CSU, 2987 CSU, 2998CSU , 1480E TVM 1466 MU, 1467 SU, 2066 U, 2067 MU, 2067 SU, 2082 BAU TVS 1456 M, 1457 M, 1457 S, 1458 S, 1459 ST, 1466 MU TVS 1466 SAP, 1468 U, 1482 EAV, 2056 M, 2057 M, 1480/1484GAV TVS 2057 S, 2058 S, 2066 MU, 2068 U, 2082 M, 2083 BAW / 2084 TVS 2175 SU, 2175U. TS 149CR, 209CR, 2070, 2070E , 2080M , 2157 MFS	ST - 01
<b>AT 2079 / A1</b>	<b>&amp;</b> TVC 102 (Modelo novo, não é compatível c/102 TR (antigo)/ 1021 / 1022 ( Vide NF 7305 ) (LER MANUAL) / TV 7022K	ST - 02
<b>OV 2094 / AO</b> OV 2094 / AO 08231 FT ----	TV 1484 , 1491 , 2084HAV	ST - 03
<b>B 32 - 3416</b>	TVC 10 ILX (DUPLICIDADE)	ST -
<b>B 32 - 3423</b>	TVC 100	ST -
<b>TFB 4029 AD</b>	CF 2051 A	ST -
<b>TFB 4030 AD</b>	<b>14 "</b>	ST -
<b>TFB 4034</b>	TS 140, 141, 142, 161, 201, 202, 204, 207VS CR / TVC 165 TVC 145 - CR / TVC 160 / TVC 164 / TVC-208VS / 200A / TVC 140	ST - 08
<b>TFB 4048 BD</b> TFB 4065	TS 147, 147VS-CR, 167, 167 CSCR, 207, VS / 2, TS 168 , TS 152 , TS 208VC-145VS-A, TVC 205 , 206 VS , TVC 200	ST - 09
<b>TFB 4059 AD</b>	TVC 206 VS - SÉRIE F , TVC 3064 / 3485P	ST -
<b>TFB 4062</b>	TS 287	ST - 11
<b>TFB 4069 AD</b>	210R6B, 215R8F, 259D9B	ST -
<b>TFB 4086</b> TFB 4087	TS 2889F, TS 285 ST / PIPTS 289 ST	ST - 13

**TOSHIBA**

<b>TFB 4100 AD</b>	2985 S / 2996-S (DUPLICIDADE) / CN 27D48 (DUETO)	ST -
<b>TFB 4121 BD</b>	TV 2986 S , 2996 S (DUPLICIDADE)	ST -
<b>TFB 4126 BR</b> TFB 4126 AE TFB 4126 CS  TF B 42 03 A1	TV 1484 , 2078 FM , 2079 FMS, TV 2083 FAV E 14", 2084HAVTV 2089H / 2090 I , 2090, 2082, 2084 TV 2096ST / GMS / HMS / TV 2088 I / LUMINA NOVA TV 2084, 2085, 2086, 2087, 2090	ST - 16
<b>TFB 4127 RE /</b>	TV 10R22EA, 1022BAV, U8, U9	ST -
<b>TFB 4129 AD</b>	2966 S	ST -
<b>TFB 4130 AD</b>	3466P, 3486P , CE 36G1 8 , CN 32G90	ST -
<b>TFB 4131 DD</b>	2987 SU, 2997 SU, 2997 P	ST -
<b>TFB 4132 DH</b> TFB 413 2 CD TFB 413	TV 2987SU, 2997P, 2997SU , 2998ASU 29A87, 29A97SU, 34A88P, 34A88SU TV 3488P, 3888P	ST - 21
<b>TFB 4134 AE</b> TFB 4134 AB	TV 1478 FM, 1483 FAV , TV 2080 E, 1488 FMU11 / TV 1484 / 1484-G TV 1485 / TV - 1490 / 1482	ST - 22
<b>TFB 4151 AD</b> TFB 4151 BE TFB 4151 BH	2987 CS, 2987 CSU, 2987 DS, 2998 CS, 2998 CSU / 2987EMS	ST - 23
<b>NF 7304 ST</b>	<b>&amp;</b> TVC 100 (DUPLICIDADE)(LER MANUAL)	ST -
<b>NF 7305</b>	TVC 10, TVC 100CR , 102 TR (Modelo Antigo)	ST -
<b>KF 7414</b>	<b>&amp;</b> TVC 10 i L(LER MANUAL)	ST -
<b>TFB 4118 ZD</b>	29 BC 55 , 29 S 55 ST , CN 35 D 90	ST -
<b>TFB 4099 AD</b>	TVC 3064 , TVC 3485 , TVC 3485P	ST -
<b>TFB 3058B</b>	6"	ST -
<b>TFB 4156AD</b>	2955 DFP / 2956 DFP / 3455 DFP	ST -
<b>TFB 4210AH</b> BW 03041	TV 2987 IMS / 2981 JAVS CHASSIS 5 e 6 TV 2999 / 2987 JMS	ST - 31

<b>TFB 4182 AH</b> BW02702	TV 2957 / TV 2958/1 PT OCCU DUPLO	ST - 32
<b>TFB 4192 AS/ AF</b>	TV 2958 / TV 3489	ST - 33
<b>TFB 4167 BH</b>		ST -

BW 02003		
TFB <del>4210</del> <b>4198</b> / AJ		
13320025D		
<b>TFB 4198BE</b>	TV 2999	ST -
<b>TFB 4212AF /</b>	TV 2959 / 2958 GFS / 2921 GFS	ST -
<b>TFB 4039 AD</b>	29"	ST - 38
<b>BSC 23-N0104</b>		<b>ST -</b> 38

**ZENITH / GE**

<b>FCV 2010 E 09A</b> 230934	RDA 1420 ( Vide Equivalente Gradiente - GT-06 ) 14 GE 00	ZT - 01 GT - 06 RCA - 08
<b>9504372</b>	CHASSIS: SAR, SAY e SAM - 2053 C222BT - 20 Polegadas, SAM 21494 , 2153 BT - 21 Polegadas / 2953 BT - 29 Polegadas/ 3453 BT - 34 Polegadas	ZT - 02
<b>95-4134-15</b>	PUY 5263DT , PVR 5263 - 4660 , PVR 6069 , PVY 6069	ZT - 02
<b>95-4134-01</b>	FR 3547DT / SY 3581 DT / (FR-3587BT : NÃO É UTILIZADO FOCUS SCREEN)	ZT - 04
<b>95-4134-07</b>	38"	ZT - 04

**ZENITH / GE**

<b>95-4134-11</b> EIA 343	<b>&amp; SR-3547 DT (LER MANUAL) PZR 5263DT</b>	ZT - 06
<b>95.4438</b> FEC 22		ZT - 07
<b>A 17196 - 12</b> DIVISOR DE FOCUS	RETROPROJETOR 60" (LER MANUAL) (COLOCAR VENTUINHA)	ZT - 08
<b>154 - 168 G</b>	FLIPERAMA / VIDEO GAME / VIDEO BINGO	FLIP - 04
<b>KFS 60291</b>	FLIPERAMA / MÁQUINA FOTOGRÁFICA NEOPRINT	FLIP - 02
<b>3121.218.30121</b>	FLIPERAMA / VIDEO GAME / VIDEO BINGO	FLIP - 02
<b>43-73-1001 B</b>		DV - 01
<b>FCK 14 A 032</b>		DV - 01
<b>MSU1FVG213</b>	CCE	DV - 03
<b>154-279R</b>	CCE	DV - 01
<b>CF-33661</b>		DV - 01
<b>CJ 27253 + CJ 27296</b>	<b>JVC 35" ORIGINAL SOB CONSULTA</b>	DV - 06
<b>CE 42485</b>	<b>JVC ORIGINAL SOB CONSULTA</b>	DV - 07
<b>TFB 5057</b>		<b>DV - 07</b>
<b>BSC 24-3910M</b>		<b>DV - 08</b>

**FOCUS SCREEN 900**

<b>2M31 9K / WBL13H</b>	MAGNETRON PARA MICROONDAS - SAMSUNG 2M219K / 2M319K / 2M210-M1 / OM75P(31) / OM75S(31)	901
<b>2M219H / WBL13E</b>	MAGNETRON PARA MICROONDAS 2M167B M-16 / 2M167B M-147 / 2M240H / 2M210 M-62	902
<b>2M219J</b>	MAGNETRON PARA MICROONDAS 2M2169J	903
<b>2M319J / (2M213)</b>	MAGNETRON PARA MICROONDAS OM75D(10) / 2M172A / 2M213 / 2M214 / 2M218J / 2M246 / 2M319J	904
<b>6174V - 8004 A</b> 6174V - 8004 D 6174V - 8005 C 570007001908	GRADIENTE - MONITOR DE SEGURANÇA SM-14 / CFTV / CFTV SM-20	800
<b>BSH-7</b>		801
<b>BSH-12N05D</b>		803
<b>BSH-13</b>		805
<b>BSH-14N304L</b>		806